



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 24, 2013

Reviewed: _____

Mine Name: Ticaboo Stockpile Removal	Permit Number: S/017/0001
Operator Name: Ucolo Exploration Corporation	Inspection Date: May 21, 2013
Inspector(s): Wayne Western	Time:
Other Participants: John Reay, BLM	Mine Status: ACT
Weather Condition: 70's clear skies	Last Inspection: May 13, 2013
Bond Renewal Date: 2017	Bond Amount: \$34,000.00
Surface Ownership: BLM	Mineral Ownership: BLM
Last Year of Production: NA	Acreage: 7 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The bond is due for escalation in November 25, 2013.

The Operator has paid the 2013 annual fee and given the 2012 annual report.

There were tracks on the stockpile. It appears that there has been some activities on the site recently.

Conclusions and Recommendations:

The Division should continue to monitor the site.


Inspection Date: May 24, 2013

Page 2 of 4

S/017/0001

Directions to Site:

Inspector's Signature

A handwritten signature in cursive script, appearing to read "Wayne Walters", written over a horizontal line.

WHW:

cc: (OPERATOR)

agencies

H:\Inspection Report\ins-template.portrait.final.doc



West side stockpile



Recent tracks



East side



East side